



Ag Testing - Consulting

Account No. : 42961

Water Analysis Report

SHEARER, JASON  
10373 CROOKED CREEK LN  
DENHAM SPRINGS LA 70726

Invoice No. : 1086769  
Date Received : 05/20/2011  
Date Reported : 05/23/2011  
Lab Number : 2521

Results For : JASON SHEARER  
Location : #1 PLAIN TAP  
Sample ID :

pH	8.5
Total Dissolved Solids (TDS) Est	200
Electrical Conductivity, mmho/cm	0.33
Cations / Anions, me/L	3.5 / 3.4

	ppm
Sodium, Na	80
Potassium, K	< 1
Calcium, Ca	< 1
Magnesium, Mg	< 1
Total Hardness, CaCO <sub>3</sub>	3
Nitrate, NO <sub>3</sub> -N	0.1 (SAFE)
Sulfate, SO <sub>4</sub> -S	3
Chloride, Cl	5
Carbonate, CO <sub>3</sub>	9
Bicarbonate, HCO <sub>3</sub>	166
Total Alkalinity, CaCO <sub>3</sub>	151

"<" - Not Detected / Below Detection Limit



Ag Testing - Consulting

Account No. : 42961

Water Analysis Report

SHEARER, JASON  
10373 CROOKED CREEK LN  
DENHAM SPRINGS LA 70726

Invoice No. : 1086769  
Date Received : 05/20/2011  
Date Reported : 05/23/2011  
Lab Number : 2522

Results For : JASON SHEARER  
Location : #2 FILTERED TAP  
Sample ID :

pH	8.9
Total Dissolved Solids (TDS) Est	202
Electrical Conductivity, mmho/cm	0.34
Cations / Anions, me/L	3.5 / 3.3

	ppm
Sodium, Na	79
Potassium, K	< 1
Calcium, Ca	< 1
Magnesium, Mg	< 1
Total Hardness, CaCO <sub>3</sub>	< 1
Nitrate, NO <sub>3</sub> -N	< 0.1 (SAFE)
Sulfate, SO <sub>4</sub> -S	4
Chloride, Cl	7
Carbonate, CO <sub>3</sub>	12
Bicarbonate, HCO <sub>3</sub>	151
Total Alkalinity, CaCO <sub>3</sub>	144

"<" - Not Detected / Below Detection Limit